




ADDRESS: 11344 Coloma Rd, Rancho Cordova, CA 95670, USA BUSINESS NAME: DEV_STAGING ENGAGING CONTACT NAME: Dev Team APN: 06901100090000



Condition Risk Rating

CONFIDENTIAL





ADDRESS: 11344 Coloma Rd, Rancho Cordova, CA 95670, USA

Site Summary

LAND USE: Office Bldg (multi-story)	LOT SIZE: 392,911 sq ft
PARCEL NUMBER: 069-0110-009-0000	ACRES: 9.02
PARCEL CENTROID: 38.62031, -121.25968	FIPS CODE: 06067
JURISDICTION: Sacramento County	TOPOGRAPHY:
ASSESSED LAND VALUE: \$2,734,114	ELEVATION: 117.42 feet
ASSESSMENT YEAR: 2021	SLOPE: 1.58 degrees, Flat to Very Low
LEGAL DESCRIPTION: PARCEL MAP, LOT 1	

LOW





Building Summary

YEAR BUILT: 1984	CONSTRUCTION QUALITY: Average
BUILDING COUNT: 0	CONSTRUCTION TYPE: Framing, Steel
BUILDING AREA: 140,549 sq ft	EXTERIOR: Precast Concrete Panel
STORIES: 2	ROOF COVERING: Built-up Tar And Gravel
AMENITIES:	ROOF YEAR: 2015
REPLACEMENT COST: \$215.68 per sq ft	ROOF EUL: (2037)
FULL REPLACEMENT EST: \$30,313,608.32	ASPECT: 93.19 degrees/SouthEast
ASSESSED IMP VALUE: \$6,513,627	

Owner Summary

CURRENT OWNER: GOLD RIVER GPRV 14 LLC	
LAST SALE DATE: 20161209	EST MORTGAGE BALANCE: \$9,321,000
LAST SALE PRICE: \$8,625,000	TOTAL OPEN LIENS: \$9,321,000
TITLE COMPANY: PLACER TITLE COMPANY	TAX AMOUNT: \$113,662.76
LENDER NAME: CITY NATIONAL BANK	TAX RATE CODE: 54-460
LOAN TYPE: Building or Construction Loan	TAX DELINQUENT YEAR:
LOAN AMOUNT: \$9,321,000	





Hazard Risks

Drought	ELEVATED
Catastrophic Flood	ELEVATED
Mold	MODERATE
Fault Earthquake	LOW
Earthquake	LOW
Hail	LOW
Convection Storm	LOW
Lightning	LOW
Flood	LOW
Radon	LOW
Volcano	LOW
Wildfire	LOW
Wind	LOW
Tornado	LOW
Ice Dam	LOW
Frozen Pipe	LOW
Snow Load	LOW
Slope	LOW





Property Condition Insights

CATEGORY	ТҮРЕ	DATE
	Wind Damage	
DAMAGES	Water Damage	
DAMAGES	Seismic Damage	
	Fire Damage	2015-11-03
	Wind Damage Prevention	
PREVENTATIVE	Sprinkler Systems	
PREVENTATIVE	Seismic Damage Prevention	2014-08-05
	Fire Alarm	
	Solar	
IMPROVEMENTS	Alteration/Remodel/Addition	2016-01-25
IMFROVEMENTS	Repair/Replace	2015-11-03
	Demolition	2015-09-16
	Building	2016-01-25
MAJOR SYSTEMS	Electrical	2017-09-01
MAJOR STSTEMS	Mechanical American	2017-11-27
	Plumbing	





Recent Permit Activity

PERMIT DATE: 2017-11-27

VALUATION: \$9,000

PERMIT TYPE	Miscellaneous Combo Commercial
PERMIT STATUS	Completed
WORK CLASS	
DESCRIPTION	Area: C01: 11344 Coloma Road HVAC Heat Pump package unit, roof top, 5 tons, no ductwork, increase of weight with structural calculations

PERMIT DATE: 2015-11-03

VALUATION: \$4,000

PERMIT TYPE	Building Combo Repair Commercial
PERMIT STATUS	Completed
WORK CLASS	Replace Windows or Siding, Fire Repair
DESCRIPTION	AREA: C01 COM-REPAIR STAIRS 3 INSPECTIONS-COM-REPAIR STAIR LANDING WOOD SUPPORT STRUCTURE LIKE FOR LIKE OF NORTH AND SOUTH STAIRWELLS LOCATED BETWEEN BUILDINGS 100 AND 200

PERMIT DATE: 2015-09-16

VALUATION: \$115,861

PERMIT TYPE	Building Combo Alt TI Commercial
PERMIT STATUS	Completed
WORK CLASS	Alteration, Tenant Improvement
DESCRIPTION	AREA: C01 ANDREWS CONSTRUCTION COM-21- INSPECTIONS- INTERIOR TENANT IMPROVEMENT TO EXISTING SUITE TO CREATE DENTAL OFFFICE ON THE FIRST FLOOR. INCLUDES, DEMO, DOORS, PAINT, HVAC, PLUMBING AND ELECTRICAL. 1640 SQFT., CH01- SUBMITTAL OF PLAN CHANGE FOR AN ADDITIONAL SUB-PANEL.





Recent Permit Activity

PERMIT DATE: 2015-01-27

VALUATION: \$60,000

PERMIT TYPE	Re-roof Combo Commercial
PERMIT STATUS	Completed
WORK CLASS	Re-Roof
DESCRIPTION	AREA: C01 11344 COLOMA RD COMMERCIAL 8 INSPECTIONS TEAR-OFF/REROOF INSULATION BOARD OVER EXISTING SHEATHING 165 SQUARE'S OF SINGLE PLY

PERMIT DATE: 2014-09-02

VALUATION: \$3,000

PERMIT TYPE	Miscellaneous Combo Commercial
PERMIT STATUS	Completed
WORK CLASS	
DESCRIPTION	AREA: C01 AROMA OF EUROPE BAKERY INSTALL RE-LOCATED KITCHEN EQUIPMENT UNDER EXISTING HOOD, CONNECT TO EXISTING GAS PIPING. NO ELECTRICAL, EQUIPMENT TO PLUG INTO EXISTING 20a ELECTRICAL OUTLET.

PERMIT DATE: 2014-08-05

VALUATION: \$900

PERMIT TYPE	Building Combo New Add Foundation Comm
PERMIT STATUS	Completed
WORK CLASS	New Buildings, New added square footage
DESCRIPTION	AREA: C01 new exterior closet for propane tank COMMERCIAL-ADDITION OF 2X2 RATED CLOSET @EXTERIOR FOR 5 GALLON PROPANE TANK TO BE PIPED INTO SUITE W/ HALF INCH PROPANE GAS SUPPLY LINE TO TERMINATE @ EACH SHUT OFF VALVES LOCATED IN INTERIOR WALL





Recent Permit Activity

PERMIT DATE: 2013-05-06

PERMIT TYPE	Re-roof Combo Commercial
PERMIT STATUS	Completed, Completed
WORK CLASS	Re-Roof
DESCRIPTION	AREA: C01 The Fivey Co. reroof EReroof: BUR rear-off, install TPO

PERMIT DATE: 2011-11-10

VALUATION: \$4,000

VALUATION: \$43,934

PERMIT TYPE	Building Combo Repair Commercial
PERMIT STATUS	Finaled
WORK CLASS	Repairs
DESCRIPTION	AREA: C01 Club Center stair repair Violation, repair existing stairs and siding, landings like for like servicing bldgs 400-600 (middle staircase)

PERMIT DATE: 2011-07-21

VALUATION: **\$100,000**

PERMIT TYPE	Building Combo Alt TI Commercial
PERMIT STATUS	Finaled
WORK CLASS	Alteration, Tenant Improvement
DESCRIPTION	AREA: C01 The Fivey Co. Tenant Improvements in Bldg 300 Tenant Improvements to be done in Bldg. #300

PERMIT DATE: 2009-09-29

VALUATION: **\$90,431**

PERMIT TYPE	Re-Roof Combo Commercial
PERMIT STATUS	Finaled
WORK CLASS	Re-Roof
DESCRIPTION	AREA: C01 FIVEY GP Re-roof E~COM~Re-roof 250sq





REPORT USAGE

THIS **PROPERTY CONDITION PRESCREEN** REPORT HAS BEEN PREPARED FOR THE EXCLUSIVE USE OF THE CLIENT. USE BY ANY OTHER PARTY IS STRICTLY PROHIBITED WITHOUT THE WRITTEN AUTHORIZATION OF CRETELLIGENT. USE OF THIS **PROPERTY CONDITION PRESCREEN** REPORT BY THE CLIENT IS SUBJECT TO THE TERMS, CONDITIONS, AND LIMITATIONS BELOW AND/OR IN ACCORDANCE WITH CRETELLIGENT'S TERMS & CONDITIONS AND/OR ENGAGEMENT AGREEMENT FOR THIS **PROPERTY CONDITION PRESCREEN** REPORT. THIS **PROPERTY CONDITION PRESCREEN** REPORT IS VALID FOR 30 DAYS FROM THE DATE OF COMPLETION.

LIMITATIONS OF LIABILITY

TO CONDUCT THE LIMITED SCOPE OF SERVICES IN PREPARATION OF THIS PROPERTY CONDITION PRESCREEN REPORT FOR THE SUBJECT SITE, CRETELLIGENT CONSULTED INFORMATION FROM SOURCES THAT ARE COMMON AND STANDARD TO THE COMMERCIAL REAL ESTATE DUE DILIGENCE INDUSTRY. CRETELLIGENT BELIEVES THESE SOURCES ARE RELIABLE AND TRUE AND CORRECT. HOWEVER, CRETELLIGENT HAS MADE NO INDEPENDENT INVESTIGATION VERIFYING ACCURACY OR COMPLETENESS OF THE SOURCE INFORMATION RELIED UPON TO PREPARE THIS PROPERTY CONDITION PRESCREEN REPORT AND CRETELLIGENT CANNOT AND DOES NOT WARRANT OR GUARANTEE THAT THE INFORMATION PROVIDED BY THESE OTHER SOURCES IS ACCURATE OR COMPLETE. CRETELLIGENT UNDERTAKES NO RESPONSIBILITY FOR THE ACCURACY OF SUCH SOURCE INFORMATION. SPECIALIZED EXPERIENCE OR KNOWLEDGE OF THE CLIENT, SUBJECT SITE PURCHASE PRICE INFORMATION, SUBJECT SITE DEED RESTRICTIONS OR LAND USE LIMITATIONS, SUBJECT SITE INSTITUTIONAL CONTROLS OR ENGINEERING CONTROLS, AND/OR SUBJECT SITE ENVIRONMENTAL LIEN INFORMATION WERE NOT PROVIDED BY THE CLIENT TO CRETELLIGENT. IN CONDUCTING THE LIMITED SCOPE OF SERVICES DESCRIBED IN THIS PROPERTY CONDITION PRESCREEN REPORT, CERTAIN SOURCES OF INFORMATION AND PUBLIC RECORDS WERE NOT AND WILL NOT BE REVIEWED BY CRETELLIGENT. IT SHOULD BE RECOGNIZED THAT POTENTIAL ENVIRONMENTAL POINTS OF INTEREST MAY BE DOCUMENTED IN SUCH OTHER SOURCES AND RECORDS. NEITHER CLIENT'S ENGAGEMENT OF CRETELLIGENT TO CONDUCT THIS PROPERTY CONDITION PRESCREEN REPORT, NOR THE COMPENSATION FOR IT, IS CONTINGENT UPON THE RESULTS OF THIS PROPERTY CONDITION PRESCREEN REPORT, CRETELLIGENT HAS NO PERSONAL INTEREST IN OR CONCERNING THE SUBJECT MATTER OF THIS PROPERTY CONDITION PRESCREEN REPORT OR ANY PARTIES WHO MAY BE PARTY TO FINANCIAL TRANSACTIONS INVOLVING THE SUBJECT SITE COVERED BY THIS PROPERTY CONDITION PRESCREEN REPORT. THIS PROPERTY CONDITION PRESCREEN REPORT SHALL BE GOVERNED BY AND CONSTRUED IN ACCORDANCE WITH THE LAWS OF THE STATE OF CALIFORNIA (WITHOUT REGARD TO ITS CONFLICTS OF LAWS PROVISIONS). BY ORDERING THIS PROPERTY CONDITION PRESCREEN REPORT, CLIENT AGREES THAT SACRAMENTO COUNTY CALIFORNIA SHALL BE THE VENUE OF ANY ACTION REGARDING THIS PROPERTY CONDITION PRESCREEN REPORT

NO WARRANTY EXPRESSED OR IMPLIED IS MADE CONCERNING THIS **PROPERTY CONDITION PRESCREEN** REPORT. CRETELLIGENT SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE, PURPOSE, OR RELIANCE. ALL RISK IS ASSUMED BY THE CLIENT. IN NO EVENT SHALL CRETELLIGENT BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. THE CLIENT ACCEPTS THIS **PROPERTY CONDITION PRESCREEN** REPORT "AS IS". ANY ANALYSES, ESTIMATES, RATINGS, CONDITION RISK RATINGS, LEVELS, RISK CODES, OR OTHER INFORMATION PROVIDED IN THIS **PROPERTY CONDITION PRESCREEN** REPORT ARE FOR ILLUSTRATIVE PURPOSES ONLY, AND ARE NOT INTENDED TO PROVIDE, NOR SHOULD THEY BE INTERPRETED AS PROVIDING, ANY FACTS REGARDING, OR PREDICTIONS OF, ANY CONDITION ORIENTED RISK FOR ANY PROPERTY. THE **PROPERTY CONDITION PRESCREEN** REPORT IS NOT A SUBSTITUTE FOR A PROPERTY CONDITION ASSESSMENT (PCA). THE CONDITIONS AFFECTING THE SUBJECT SITE ARE UNKNOWN AND CRETELLIGENT MAKES NO REPRESENTATIONS REGARDING ANY SUCH CONDITIONS.